
on/off switch
on/off switch
on/off switch
on/off switch
1n4007
Fuse 5A
12v in
100ohm
100uF
555NE
10k pot
50k pot
10nF
10uF
1uF
47uF
on/off switch
connection generator to pulser
measuring point
Lorlin 3x4
generator part
100ohm
100uF
555NE
10k pot
measuring point
50k pot
10nF
100nF
220nF
10nF
220 Ohm
IRFP640
G
D
S
820 Ohm
Lorlin 3x4
generator part
4x Z586 zener
start
end
bifilar coil
end
to minus poles cell
start
to plus poles cell